



WEBSERVER PRONET

1-017-521

149. Connection diagram



- 1 Sauna 1 RS485 connection
- 2 Sauna 2 RS485 connection
- 3 5 V DC mains input
- 4 Ethernet RJ45
- 5 Mini-USB (not in use)
- 6 RS485 transmission indicator lamp
- 7 RS485 reception indicator lamp